Danfoss A/S
6430 Nordborg
Denmark
CVR nr.: 20 16 57 15

Telephone: +45 7488 2222
Fax: +45 7449 0949

MANUFACTURER'S DECLARATION

Danfoss A/S

Danfoss Commercial Compressors

declares under our sole responsibility that the

Product category: Compressors + Accessories/Spare parts

Type designation(s):

Compressors type:

VZH052CGAMA, VZH065CGAMA
VZH052CJAMA, VZH065CJAMA
VZH052CHAMA, VZH065CHAMA

Accessories/Spare parts type:

Danfoss code number	Product description
120Z0059	Belt type crankcase heater, 65 W, 230V, CE mark, UL (Wire length: 1000 mm)
120Z0060	Belt type crankcase heater, 65 W, 400 V, CE mark, UL (Wire length: 1000 mm)
120Z5012	Belt type crankcase heater, 70W, 460V, CE mark, UL
120Z5013	Belt type crankcase heater, 70 W, 575V, CE mark, UL
120Z0958	120Z0958 Belt type crankcase heater, 55W, 230V, CE&UL
120Z1011	C-HEATER BELT 55W 230V SILICONE CE
120Z0892	CRANKCASE HEATER 230V 65W
120Z0894	CRANKCASE HEATER 400/460V 65W -70 FRAME
7750009	Discharge thermostat kit
7973008	Discharge thermostat kit
120Z0823	Discharge temperature sensor/converter
120Z0158	Discharge temperature sensor
120Z0824	Discharge temperature converter
120Z0803	Oil level switch-electrical part(24V AC/DC) with relay*
120Z0804	Oil level switch-electrical part(230V AC) with relay*
034G7073	M12 angle female connector cable 2m
034G7074	M12 angle female connector cable 8m
120Z0581	LCP display
120Z0326	Inverter, LCP display

Danfoss only vouches for the correctness of the English version of this document. In the event of the document being translated into any other language, the translator concerned must be liable for the correctness of the translation.

Covered by this declaration is in conformity with the following directive(s), regulations(s), standard(s) or other normative document(s), provided that the product is used in accordance with our instructions.

The products covered by this declaration are considered not to be source of ignition caused by temperature and arcs/sparks when located in enclosures/areas where stagnation of corresponding A2L refrigerants specified in instructions may occur due to abnormal situation of a leakage in the refrigeration system.

The products comply with IEC/EN 60335-2-34, IEC/EN 60335-2-40, cl. 22.114, cl.22.116, cl. 22.117 in normal and abnormal conditions, and are not considered as source of ignition.

Date: 2025.12.01 **Place of issue:** 490 Rue du Pou du Ciel Zone Industrielle des Communaux 01600 Reyrieux	**Issued by** **Signature:** **Name:** Sravan Kumar Konda **Title:** Chief Engineer	Date: 2025.12.02 **Place of issue:** 490 Rue du Pou du Ciel Zone Industrielle des Communaux 01600 Reyrieux	**Approved by** **Signature:** **Name:** Philippe Duchene **Title:** CC-S&R Head

Danfoss only vouches for the correctness of the English version of this document. In the event of the document being translated into any other language, the translator concerned must be liable for the correctness of the translation.